$model \ no:$

SG151D, SG151P SG155D, SG155P



SIGNATURE SERIES

46" ROUND AND SQUARE 3 SEAT PORTABLE ADA ACCESSIBLE TABLE EXPANDED METAL & PERFORATED

(C) Wabash Valley Manufacturing, Inc.

customer service:

ASSEMBLERS: If you find any parts missing or damaged, or if you're having difficulty assembling your furniture/equipment, call us at:

* Before calling, have your product model number available.

1-800-253-8619 (Inside U.S.A.) 260-352-2102 (Outside U.S.A.) Monday thru Friday, 8:00 AM — 4:30 PM Eastern Time (EXCEPT HOLIDAYS)

Any correspondence concerning our product should be sent directly to our Customer Service Manager at:

Wabash Valley Manufacturing, Inc. 505 É. Main Street P.O.Box 5 Silver Lake, IN 46982 U.S.A. FAX: 260-352-2160

maintenance:

Regular inspection and maintenance of all parts, and fasteners is necessary. Tighten all bolts and nuts. Inspect Tops, Seats, Legs, Braces and Fasteners periodically for wear or vandalism. Replace broken or worn parts immediately or take equipment out of service Use génuine Wabash Valley replacement parts. until repairs are made.

To restore plastisol coating to its luster after prolonged use, wash/rinse/dry and use Armor-All ® or similiar quality vinyl protectant.

KEEP THIS ASSEMBLY/SPECIFICATION SHEET FOR FUTURE REFERENCE.

specifications:

NOTE: We reserve the right to change specifications without notice.

Heat fused poly-vinyl coating, finished on inner-metal structure, to an approximate 3/16" thickness. Framework assemblies are finished with powder coating; electrostatically applied and oven cured according to powder manufacturer's specifications. Fasteners are stainless steel to resist corrosion.

TABLE FRAME:

Main support is constructed of 1 5/8" od x 14 gage structural steel tubing. Mounting brackets on legs are 1/4" x 1 1/4" steel flat bar. Cross brace is constructed of 1" od x 15 gage structural steel tubing. Handicap leg base plate consists of 7 gage steel.


TOP & SEAT:


Top and seats use fabricated 3/4" #9 expanded steel mesh and perforated is 12 gage sheet metal. Framing for top consists of die formed 14 gage mitred angles 3/4" x 1 3/4". The top's square frame mounting brackets are 1/4" x 3" and 1 1/2" steel flat bar. The seat's mounting brackets are 1/4" x 1 1/2" steel flat bar. The top's standard corner support braces are 1/8" x 1 1/2" steel flat bar.

SG155D and SG155P ground space requirements are 69 1/2" x 74 3/8". The table top is 55 1/2" x 46 3/8" and 30 1/2" to the top of the table. Seats are 10 3/8" wide, 36 3/8" long and 19 5/8" to the top of the seat. Corner radius is 3" to the outside.

SG151D and SG151P ground space requirements are 77" x 78 3/4". The table top is 60 1/2" x 46 3/8" and 30 1/2" to the top of the table. Seats are 10 1/2" wide, 34 3/8" long and 19 5/8" to the top of the seat.

NOTE: When Umbrellas are used on Tables, the Umbrellas must be secured. Wabash Valley Umbrellas include an Umbrella Collar for securing.





$assembly \ procedures:$ IMPORTANT: Assemblers should be reasonably skilled in the assembly of commercial grade/heavy duty fabricated steel equipment.

To ensure proper assembly, it is suggested that you take adequate time to locate and identify each part. To prevent scratching of the finished pieces, we recommend this unit to be assembled on a clean, flat, solid, surface with a drop cloth, allowing plenty of working room. Also please read the instructions and study the sketches very carefully. A little extra time spent before assembly will be well worth it in performing a complete, proper assembly. Please note that all parts have been precut and pre-drilled.

During the assembly process leave all bolts and nuts "finger tight", until the entire unit is completely assembled. This allows room for movement to level or adjust all seats, tops, benches, framework and braces if necessary.

After final adjustment and leveling After final adjustment and leveling, permanently tighten all nuts, bolts and fasteners.

STEP 1

Invert the (A—) top so it's upside down on a flat surface. Attach (C1) and (D1) left and right legs to the outside corner of the top's square mounting frame. Attach (D1) and (C2) left and right legs to the opposite corner toward the handicap side, see FIG. 1.

Secure the top end of the legs to the outside of the top's center square mounting frame, using one, per each leg, (F) and (I) using two (H) and one (J) per (F).

NOTE: The tabs of each leg should meet at each corner when installing the legs. Temporarily insert one (G), (I), (J) and two (H) loosely into the tab holes of each leg. This allows the legs to secure and hold each other in place at each corner.

Repeat STEP 1 for the other side to complete the installation of all legs. Make sure each leg is properly attached in all four corners of the top's center square mounting frame.



Attach all four ends of the (E) cross brace, where the tabs of each leg meet. Use the bolts which temporarily secured each leg together. see FIG. 2.

NOTE: Before attaching the cross brace, make sure the round cylinder at the center of the cross brace is pointing downward toward the bottom side of the top.

STEP 3

Check all fasteners making sure each fastener is finger tight and properly supporting the unit. Re-invert the table to its' topside up position.

STEP 4


STEP 5

AI260L

the required tools.

Lift one (B—) seat above the seat end of each leg, on one side of the unit. Bring the seat down, aligning the mounting brackets, one each leg, to the inside of the seat's mounting brackets, see FIG. 3. Secure the seat using two, per each mounting bracket, (F) and (I) using two (H) and one (J) per (F).

Repeat STEP 4, to attach the remaining seats.



installation: WARNING: The proper installation for Wabash Valley products may depend upon many factors unique to the site, location, or use of a particular product. Consult with your contractor or other professional to determine your specific installation requirements.





FIG. 2

product dimensions:

SG155D, SG155P



SG151D, SG151P

